

# Composite fabrication via VARTM Process

*Birendra Chaudhary*

**Department of Mechanical, Industrial and  
Systems Engineering**

# METHODS USED IN MANUFACTURING OF COMPOSITES

- **Wet lay-up method**

Wet composite is rolled by hand to evenly distribute the resin and thereby removing the air pockets

- **Pultrusion**

Continuous reinforcement fibers are impregnated with resin and passed through a die

- **Resin transfer molding (RTM)**

Mold is loaded with the reinforcement material and then closed

Resin is injected at the center of the top surface of the mold

- **Vacuum Assisted Resin Transfer Molding (VARTM)**

Dry preform is placed into the tool and vacuum bagged in conjunction with resin distribution and vacuum distribution lines

# VACUUM ASSISTED RESIN TRANSFER MOLDING (VARTM)

- Relatively low cost for high volume production
- Simple low-cost tooling
- Very large and complex parts are practical
- High fiber volume fraction than hand lay-up
- On site manufacturing and repairing is possible
- Reduced environmental concerns than hand lay-up as it is closed system



*Fig 1. Woven Roving E-Glass*



*Fig 1. Stitch Bonded E-Glass*

## STEPS FOR VARTM PROCESS

- Mold preparation and fabric lay up
- Sealing off the mold and running vacuum
- Resin preparation and degassing
- Resin impregnation
- Post cure of fabricated panels




Figure 1. Schematic for the Fabrication of the Composite Panel

### Mold Surface

- Fabrication of the composite panel is either a metal plate or a glass plate
- Has a provision of heating while the fabrication is in progress

### Mold Surface Protection

- Facilitates the easy removal of the panel from the mold surface after the fabrication process is over

### Fabric Lay-up

- Precaution should be taken in stacking
- Edges of the fibers should align to each other

### Top Release Fabric

- Peel ply\* is placed on the top of the stacked sequence of fabric
- allows for easy removal of the composite panel after fabrication from the vacuum bag



Fig. Experimental VARTM Setup

### Distributive Medium

- Mesh (Blue) laid on top of the top release fabric
- Maintains an even distribution of resin on the top of the panel
- Facilitates the flow of resin through the thickness of the panel

### Resin and Vacuum Distribution Line

- Spirally cut tubes are used
- Used for uniform resin distribution and vacuum line

### Sealing the mold

- Sealant tape is used

### Vacuum Bag

- Film is placed all over the mold area and is sealed firmly using special sealant tape
- Helps to maintain a uniform vacuum throughout the molding process




Fig. Experimental VARTM Setup




### Resin preparation and degassing

- Resin is mixed with catalyst, promoter and with precalculated gel time
- percentage suggested by the resin manufacturer
- Before adding the resin to the mold, it must be free of all the air pockets that may cause voids if they enter the mold
- Resin is kept in a vacuum chamber that maintains a vacuum
- This enables the suction of all the gases that have been trapped into the resin



## Resin impregnation

- Resin is mixed with catalyst, promoter and gel time retarder in the precalculated (Cobalt Nap, DMA and MEKP)
- percentage suggested by the resin manufacturer
- Before adding the resin to the mold, it has to be free of all the air pockets that may cause voids if they enter the mold
- Resin is kept in a vacuum dome that maintains a vacuum
- This enables the suction of all the gases that have been trapped into the resin






Guidelines for using Promotors and Catalyst

**TYPICAL NON REINFORCED MECHANICAL PROPERTIES AT 25°C/77°F**

Properties	Unit	Value	Test Method
Tensile Strength	psi	10,153	ASTM D 638
Tensile Modulus	Kpsi	450	ASTM D 638
Tensile Elongation	%	9.0	ASTM D 638
Flexural Strength	psi	19,580	ASTM D 790
Flexural Modulus	Kpsi	440	ASTM D 790
Heat Deflection Temperature	°C/°F	87/189	ASTM D 648
Hardness, Barcol Model 934-1	HB	35	ASTM D 2583

**GUIDELINES FOR INITIATOR AND PROMOTER ADDITIONS**

Gel Time at 18°C/ 65°F	Cobalt Nap 6%	DMA	High-Point 90 MEKP
15 +/- 5 minutes	0.60	0.40	1.50
30 +/- 10 minutes	0.50	0.20	1.50
60 +/- 15 minutes	0.30	0.10	1.50
Gel Time at 25C (77F)			
15 +/- 5 minutes	0.50	0.50	1.50
30 +/- 10 minutes	0.40	0.40	1.25
60 +/- 15 minutes	0.20	0.20	1.50
Gel Time at 0C (86F)			
15 +/- 5 minutes	0.50	0.50	1.50
30 +/- 10 minutes	0.30	0.30	1.50
60 +/- 15 minutes	0.25	0.25	1.25



**Fig. Resin Impregnation**