EN-017 EN-017 ASAF ASHRAF

Graduate School of Oceanography and Ocean Engineering University of Rhode Island Kinaston, R. I. 02881

CRUISE REPORT

R/V ENDEAVOR Cruise EN-017

Armand J. Silva, Chief Scientist Edward P. Laine, Co-Chief Scientist E. Williams, Ed.

Project: Coring Test Cruise

Funding: NSF OCE78-04380

Objectives: Testing of standard piston coring system, large diameter piston

corer, large diameter gravity corer, associated handling systems,

winch system, sediment processing operations, and 3.5 kHz

subbottom profiling system

Schedule: Departed 15 January 1978, Narragansett, R. I.

Returned 22 January 1978, Narragansett, R. I.

Study Region: Gulf Stream Outer Ridge: 36°N - 66°W

Instruments and Equipment: Standard Piston Corer (SPC)

Large Diameter (11.4 cm) Piston Corer (LDPC)

Large Diameter Gravity Corer (LDGC)

3.5 kHz ship-mounted system

Bottom camera

XBT set

Scientific Personnel:

Armand J. Silva Chief Scientist, OE Edward P. Laine Co-Chief Scientist, GSO David I. Calnan Research Associate, OE Theodore Benttinen Marine Technician, GSO Stephen Imms Marine Technician, GSO Steven Akers Research Assistant, OE David R. Carchedi Research Assistant, OE Steven Carey Research Assistant, GSO Kathryn Moran Research Assistant, OE Roger Morin Research Assistant, OE Nancy Penrose Research Technician, GSO Roger Prince

Research Technician, GSO and Brown University

Steven Sparks Research Associate, GSO Thomas S. Loutit Research Assistant, GSO

Operations

A) Pre-cruise. During the three weeks preceding departure, considerable effort was devoted to installation of special core handling equipment, modifications to the winch to increase pull-out capabilities and installation of the 3.5 kHz transducer array. A core weight cradle was borrowed from WHOI and modified to fit near the J-frame. Unfortunately the cradle design was not well suited for use on the ENDEAVOR. but it was determined to be workable. The LDPC davit/trolley system had to be modified considerably. Due to dock and ship configurations, it was necessary to turn the ship port side to the dock on the day of departure so that final fitting and installation of the outboard trolley rail could be completed.

The SPC was assembled and the cradle, core weight and corer were lashed outboard along the starboard rail during transit.

- B) Transit. Due to weather conditions, deck work was very limited during transit to the site. Security of the core weight was affected, but addition of turnbuckles to lash the cradle to the deck remedied the situation. The 3.5 kHz system was checked out during transit.
- Site Work. Work was limited by weather and sea state constraints and therefore actual time available for piston coring was quite small. Following is a brief recapitulation of events:
 - 1. Make up and load test trawl wire termination.
 - 2. Repair and adjustments to trawl winch system.
 - LDGC on trawl wire 600 lb. corer, 10 ft. barrel, 35 51.5 launching of LDGC from +barrel Corer overpenetrated but otherwise functioned well.
 - 4. Lower camera with hydrowinch (camera malfunctioned).

35 52 51 11 12 12

- 5. LDGC on trawl wire 450 lb. corer, 10 ft. barrel, 5 ft. free-fall. Launch and retrieval was efficient, but evidently lower-half core barrel was sheared off during launch--probably against side of ship during heavy roll.
- 33° 65 71.56° 57.58 6. Rig and launch <u>SPC - 3000</u> lb. core weight, 30 ft. core barrel, 17 ft. free-fall. Maneuvering of core cradle outboard in a controlled fashion was completed by rigging the hydrowire outboard on the J-frame working against a block and tackle inboard to the deck. Due to position of STD sheave with respect to the trawl wire sheave (a load cell on the trawl sheave brought the sheave in closer to the ship) and incorrect rigging, some difficulties were encountered during lowering of the trigger core. Otherwise the launch went fairly well.

The corer was triggered at the bottom but was lost due to failure of the termination at the eye socket. Failure is attributed to a combination of heavy core weight, short barrel, soft sediment and metal defect in termination.

- 7. Camera lowered strobe not working properly. One good photo obtained.
- 8. LDPC Plans were made to assemble a 40 ft. LDPC with the lighter (WHOI) core weight (1800 lb.) while steaming to a site on the Continental Slope. However, severe weather and sea state conditions made this plan inoperative, and it was necessary to abandon this part of the program.
- 9. XBT transect Due to the sea state, it was not possible to launch the XBT's,
- 10. Core processing One section of GC-1 was extruded and processed. GC-2 extruded.

Results

Following is a summary of results:

- 1. 3.5 kHz system satisfactory.
- 2. LDGC Corer works well but different launch and recovery techniques necessary.

Two cores recovered:

- GC-1 4.5 meters (1.5 meter overpenetration into core weight pipe). One section (1.5 meters) of core extruded and processed.
- 🕍 GC-2 2.5 meters (1.5 meter overpenetration into Sample disturbed and contaminated due to core barrel fracture.

 3. SPC - Corer lost. Launch operations workable. Main problem is with core weight cradle.

 4. Camera - Problems with
- photograph obtained.
- 5. LDPC Corer assembly system is functional. Extrusion system must be relocated aft to allow clearance for extrusion. Booster system for pull-out force was assembled and seems to be operational but was not put to use.
- 6. Trawl winch A number of problems were encountered, and certain modifications must be made to make the winch fully effective.

* need field data.

10 35 35 7.0 W

Summary and Recommendations

Subbottom Acoustics

The newly installed 3.5 kHz subbottom profiling system worked well.

2. Piston Coring

System changes must be made for a fully efficient large diameter piston coring operation.

Gravity Coring

It is recommended that gravity coring be done with the hydrowire off the stern with a 1/4" cable unit.

4. Winche's

All winches should be thoroughly checked, tested and maintained.

5. Core Storage

A refrigerated van should be available for core storage. The best location seems to be on the upper deck near the hydrowinch.

GC-01 35° 51.0'N: 66° 10.9'W 19/- GC-02 35° 54.2'N: 66° 14.9'W

State 17 1 25 215'N 66° 16.5 W State 17 1 25 215'N 66° 11'W State 17 1 25 215'N 66° 11'W State 17 1 25 215'N 66° 11'W