

DEM USE ONLY	
Date Received	

RIPDES SMALL MS4 ANNUAL REPORT

GENERAL INFORMATION PAGE

BIDD	ES PE	DIMIT	#RIR	0	110
KIPU	CO PC	RIVIII	#KIP	(040)	JIS

Print Title

Signature

Director of Facilities Services

RIPDES PERMIT #RIR040 <u>019</u>			
REPORTING PERIOD: X YEAR 13 Jan 2016-Dec 2016			
OPERATOR OF MS4			
Name: The University of Rhode Island			
Mailing Address: Sherman Building 60 Tootell Road			
City: Kingston	State: RI	Zip: 02881	Phone: (401) 874-5488
Contact Person: Jerome Sidio	Title: Director o	f Facilities Services	
	Email: jerrysidio	o@uri.edu	
Legal status (circle one): PRI - Private PUB - Public BPP - Pu Other (please specify):	blic/Private	STA - State	FED – Federal
OWNER OF MS4 (if different from OPERATOR)			
Name: Same			
Mailing Address:			-
City:	State:	Zip:	Phone: ()
Contact Person:	Title:		
	Email:		
CERTIFICATION			
I certify under penalty of law that this document and a supervision in accordance with a system designed to the information submitted. Based on my inquiry of the directly responsible for gathering the information, I ce knowledge and belief, true, accurate, and complete. false information, including the possibility of fine and i	assure that qual e person or pers rtify that the info I am aware that	ified personnel prop ons who manage the rmation submitted is there are significant	erly gather and evaluate e system, or those persons , to the best of my penalties for submitting
Print Name Jerome Sidio			



MINIMUM CONTROL MEASURE #1: PUBLIC EDUCATION AND OUTREACH (Part IV.B.1 General Permit)

SECTION I. OVERALL EVALUATION:

GENERAL SUMMARY, STATUS, APPROPRIATENESS AND EFFECTIVENESS OF MEASURABLE GOALS:

Include information relevant to the implementation of each measurable goal, such as activities, topics addressed, audiences and pollutants targeted. Discuss activities to be carried out during the next reporting cycle. If addressing TMDL requirements, please indicate rationale for choosing the education activity to address the pollutant of concern.

(Note: Identify parties responsible for achieving the measurable goals and reference any reliance on another entity for achieving measurable goals. Mark with an asterisk (*) if this person/entity is different from last year.)

Responsible Party Contact Name: Andy Alcusky

IV.B.1.b.1

Use the space below to provide a General Summary of activities implemented to educate your community on how to reduce stormwater pollution. For TMDL affected areas, with stormwater associated pollutants of concern, indicate rationale for choosing the education activity. List materials used for public education and topics addressed. Summarize implementation status and discuss if the activity is appropriate and effective.

The University requires all staff employees to attend training sessions annually for the proper handling of contaminants and the proper disposal of contaminants. All employees are reminded that nothing can be disposed into the storm drainage system. These safety sessions and presentations are conducted by the URI Safety and Risk Dept. Messages to educate the community also continued in the school website. The URI Cooperative Extension maintains a RI Stormwater Solutions website with educational information on sources and impacts of stormwater and steps that citizens and homeowners can take to reduce impacts such as reducing fertilizer use, keeping oil out of storm drains, using water wisely, cleaning up pet waste and recycling rainwater. It placed an article in the EcoRI news website about contaminants detected in water supplies in R.I. The CE and the URI Outreach Center* worked with communities to install and maintain rain gardens. The Outreach Center also runs an Eco-Exploration camp for school age children that provides education on stormwater and conservation.

IV.B.1.b.2

Use the space below to provide a general summary of how the public education program was used to educate the community on how to become involved in the municipal or statewide stormwater program. Describe partnerships with governmental and non-governmental agencies used to involve your community.

The University continued its support with various student groups for campus cleanup activities such as Earth Day events. Both the Cooperative Extension, the URI Outreach Center and the URI Sustainability Office* organize an annual Earth Day event on campus with booths and displays on a range of environmental topics including stormwater, water quality, recycling and land use. In what may appear as unrelated to stormwater pollution prevention, the University has entered into a contract for energy savings which includes a behavior change measure. One item discussed with all on-campus students is changing their behavior concerning trash and recycling materials. Any reduction of trash considerably helps the amount of pollution entering the storm water system. URI has constructed the Rhode Island Stormwater Management and treatment Demonstration Facility (RI SDF). This facility evaluates BMP structures against manufacturer claims and under environmental conditions prevailing in the state and is useful in training installers and regulators.

PUBLIC EDUCATION AND OUTREACH cont'd

Check all topics that were included in the Public Education and topics selected, provide the target pollutant (e.g. construction selected).	d Outreach program during this reporting period. For each of the sites, total suspended solids):
Topic	Target Pollutant(s)
x Construction Sites	TSS
x Pesticide and Fertilizer Application	Nitrogen, phosphorus
☐ General Stormwater Management Information	
☐ Pet Waste Management	
☐ Household Hazardous Waste Disposal	
x Recycling	Floatables
☐ Illicit Discharge Detection and Elimination	
☐ Riparian Corridor Protection/Restoration	
☐ Infrastructure Maintenance	
x Trash Management	Floatables
☐ Smart Growth	
☐ Vehicle Washing	
☐ Storm Drain Marking	
x Water Conservation	
☐ Green Infrastructure/Better Site Design/LID	
☐ Wetland Protection	
☐ Other:	
□ None	
Specific audiences targeted during this reporting period: x Public Employees Residential Businesses Restaurants Other:	x Contractors Developers x General Public Industries Agricultural
Additional Measurable Goals and Activities	
Please list all stormwater training attended by your staff during t position of all staff who attended the training. Trainings:	the 2016 calendar year and list the name(s) and municipal
Attending name of staff and title:Attending name of staff and title:	



MINIMUM CONTROL MEASURE #2: PUBLIC INVOLVEMENT/PARTICIPATION (Part IV.B.2 General Permit)

SECTION I. OVERALL EVALUATION:	
GENERAL SUMMARY, STATUS, APPROPRIATE	NESS AND EFFECTIVENESS OF MEASURABLE GOALS:
	h measurable goal, such as types of activities and audiences/groups next reporting cycle. If addressing TMDL requirements, please pollutant of concern.
(Note: Identify parties responsible for achieving the machieving measurable goals. Mark with an asterisk (* *	neasurable goals and reference any reliance on another entity for ') if this person/entity is different from last year.)
Responsible Party Contact Name: _Andy Alcusky	
Phone: <u>(401) 874-2448</u> Email: <u>aalcusky@ur</u>	<u>i.edu</u>
description of the groups engaged, and a addressing TMDL requirements indicate h concern. Name of person(s) and/or partie effectiveness of BMP and measurable go	
targeted include staff both educational as well as support by the students. Support staff is required to attend annual drainage system and the proper handling and disposal of campus wide cleanup to reduce floatables and Earth day and Ground Dept., the Trash and Recycling dept. the UR	•
Opportunities provided for public participation in implement Management Program Plan (SWMPP) during this reporting	ntation, development, evaluation, and improvement of the Stormwater ng period. Check all that apply:
Cleanup Events Comments on SWMPP Received Community Hotlines Community Meetings Other (describe)	 □ Storm Drain Markings □ Stakeholder Meetings □ Volunteer Monitoring ☒ Plantings
Additional Measurable Goals and Activities	
SECTION II. Public Notice Information (Parts IV.0	G.2.h and IV.G.2.i) *Note: attach copy of public notice
Was the availability of this Annual Report and the Stormwater Management Program Plan (SWMPP) announced via public notice? ☐ YES ☐ NO	If YES, Date of Public Notice: 03/01/17
How was public notified: List-Serve (Enter # of names in List:) TV/Radio Notices x Website Enter Web Page URL:	Newspaper Advertising Town Hall posting Other:
Was public meeting held? ☐ YES 💆 NO Date:	Where:
Summary of public comments received: None Received	

PUBLIC INVOLVEMENT/PARTICIPATION cont'd

Planned responses or changes to the program: None at this time.



MINIMUM CONTROL MEASURE #3: ILLICIT DISCHARGE DETECTION AND ELIMINATION (Part IV.B.3 General Permit)

SECTION I. OVERALL EVALUATION:

GENERAL SUMMARY, STATUS, APPROPRIATENESS AND EFFECTIVENESS OF MEASURABLE GOALS

Include information relevant to the implementation of each measurable goal, such as activities implemented (when reporting tracked and eliminated illicit discharges, please explain the rationale for targeting the illicit discharge) to comply with on-going requirements, and illicit discharge public education activities, audiences and pollutants targeted. Discuss activities to be carried out during the next reporting cycle. If addressing TMDL requirements, please indicate rationale for the activities chosen to address the pollutant of concern.

(Note: Identify parties responsible for achieving the measurable goals and reference any reliance on another entity for achieving measurable goals. Mark with an asterisk (*) if this person/entity is different from last year.)

Responsible Party Contact Name: Andy Alcusky

Phone: (401) 874-2448 Email: aalcusky@uri.edu

IV.B.3.b.1:

If the outfall map was not completed, use the space below to indicate reasons why, proposed schedule for completion of requirement and person(s)/ Department responsible for completion. (The Department recommends electronic submission of updated EXCEL Tables if this information has been amended.)

Number of Outfalls Mapped within regulated area: 98

Percent Complete: _100%

If 100% Complete, Provide Date of Completion: 11/2014

The outfall map was completed by the URI Utilities Dept. Outfall Location Tables have been completed and were included with the Year 5 report. The outfall map was updated in 2013 and was submitted to DEM as part of the 2013 report. The updated EXCEL tables will also be submitted (electronically) as part of this report. The Utilities Dept. used the original information from our consultant for the initial outfall map. In 2012 through 2015 the Utility Dept. expanded the list from field observations during inspections, new construction and review of plans. Eight additional outfalls were identified in 2016 with most of them associated with the construction of the new Chemistry Building.

IV.B.3.b.2

Indicate if your municipality chose to implement the tagging of outfalls activity under the IDDE minimum measure, activities and actions undertaken under the 2016 calendar year.

The University Utilities Dept chose to implement the tagging of outfalls under the IDDE minimum measure and tagged the outfalls in 2008. URI added eight outfalls to the outfall list in 2016.

IV.B.3.b.3

Use the space below to provide a summary of the implementation of recording of system additional elements (catch basins, manholes, and/or pipes). Indicate if the activity was implemented as a result of the tracing of illicit discharges, new MS4 construction projects, and inspection of catch basins required under the IDDE and Pollution Prevention and Good Housekeeping Minimum Measures, and/or as a result of TMDL related requirements and/or investigations. Assess effectiveness of the program minimizing water quality impacts.

The Kingston Campus drainage system and its records were updated during 2016. Some of the updates are a result of new construction work on campus. Areas of new construction included the new Chemistry Building, Washburn Parking Lot modifications, Tootell Road modifications and renovations at Ranger Hall. Other catch basins and drainage components were added to control flooding and erosion issues. Other catch basins and drainage structures were removed from our list since it was determined to be another MS4's responsibility. As a result of the construction activity and field inspection an additional 1 catch basin and 6 drain manholes were added to our inventory and 30 catch basins and 4 DMH's were removed from the inventory list. The entire drainage system is now recorded in GIS which allows for easier updates in the future. The changes in the quantities were a result of further mapping of the system, inspection of the system and updating changes due to recent construction. In addition to changes found during the field inspections, URI will continue to update the drainage system records as they receive the as-built drawings of the projects completed during the past calendar year. URI's Capital Projects Group provides a status of all projects on campus to the Facilities Dept. and as projects are closed out, the URI Utilities Dept. will then update the drainage records using the as-built drawings as well as any new info discovered during the yearly inspections.

IV.B.3.b.4

Indicate if the IDDE ordinance was <u>not</u> developed, adopted, and submitted to RIDEM, explain reasons why, submit proposed schedule for completion and identify person(s) / Department and/or parties responsible for the completion of this requirement.

Date of Adoption:

If the Ordinance was amended in 2016, please indicate why changes were necessary.

ILLICIT DISCHARGE DETECTION AND ELIMINATION cont'd

The University of Rhode Island has not developed this ordinance in the 2016 calendar year. The University owns the entire subject area and controls all activities on their property. The University is a state agency that has policies in place to ensure proper compliance to prohibit and enforce illicit discharges to the MS4. Policy enforcement is through a combination of inspections by Safety and Risk Management and Facilities Services Departments. The SR&M department receives, responds, investigates and files all incidents involving hazmat and other illicit discharge activities that might occur on campus. Investigations, corrective actions and enforcement activities are monitored and implemented through this office. We also conduct annual inspections throughout the campus for potential illicit discharges into the storm and waste water systems. We have developed a Spill Prevention and Containment Plan as required by the EPA that is designed to reduce the potential for illicit discharges into the sanitary and storm water systems.

IV.B.3.b.5.ii, iii, iv, & v Use the space below to provide a summary of the implementation of procedures for receipt and consideration of complaints, tracing the source of an illicit discharge, removing the source of the illicit discharge and program evaluation and assessment as a result of removing sources of illicit discharges. Identify person(s) / Department and/or parties responsible for the implementation of this requirement.

All complaints (of any nature) are referred to the URI Control Center. The Control Center will log each call and then notify the appropriate department responsible for the complaint. If the complaint is relative to an illicit discharge to the storm system, the URI Utilities Dept will be responsible to respond to the complaint. The Utilities Dept. will evaluate the complaint, trace the origin of the illicit discharge, ensure that the illicit discharge is stopped immediately and assess if other procedures need to be implemented. URI did not receive any complaints on illicit discharges in 2016.

IV.B.3.b.5.vi

Use the space below to provide summary of implementation of catch basin and manhole inspections for illicit connections and non-stormwater discharges. If the required measurable goal of inspecting all catch basins and manholes for this purpose was not accomplished, please indicate reasons why, the proposed schedule of completion and identify person(s) / Department and/or parties responsible for the implementation of this requirement. Evaluate effectiveness of the implementation of this requirement. The operator must keep records of all inspections and corrective actions required and completed.

Number of Catch Basins and Manholes Inspected for illicit connections/IDDE: __1218

Percent Complete: 99 % Date of Completion: 11/29/16

During 2016, the URI Utilities Dept. inspected all catch basins that were accessible throughout the Kingston Campus for illicit connections and non-storm water discharges. Approximately 1% of the drainage structures were not accessible (such as under platforms or large dumpsters). The inspections were performed in conjunction with the surveying of the drainage system for inventory of the system and noting condition of the structures. Inspection of the catch basins also help determined which structures were in need of cleaning. URI recorded the inspection results in an Excel database in 2016. A total of 29 Work orders were issued as a result of these inspections. In most cases, work orders consisted of catch basins requiring being rebuilt or broken grates. URI will continue to inspect 100% of the accessible catch basins in 2017

IV.B.3.b.5.vii

If dry weather surveys including field screening for non-stormwater flows and field tests of selected parameters and bacteria were not completed, indicate reasons why, proposed schedule for the completion of this measurable goal and person(s) / Department and/or parties for the completion of this requirement. Evaluate effectiveness of the implementation of this requirement. The results of the dry weather survey investigations must be submitted to RIDEM electronically, if not already submitted or if revised since 2009, in the RIDEM-provided EXCEL Tables and should include visual observations for all outfalls during both the high and low water table timeframes, as well as sample results for those outfalls with flow. The EXCEL Tables must include a report of all outfalls and indicate the presence or absence of dry weather discharges.

Number of Outfalls Surveyed Jan-Apr: <u>98</u> Number of Outfalls Surveyed Jul-Oct: <u>98</u>

Percent Complete: 100 %

Date of Completion: 8/9/2016

The University conducted two dry weather surveys in 2016. The University Utilities Dept. performed dry weather surveys on April 22, 2016 and August 9, 2016. In the first survey, flow was noted at fifteen of the outfall sites. The origin of the flow in all cases was traced back to ground water or natural flow from wet areas. Flow was observed at five of the outfalls during the August 9, 2016 survey. The results of the surveys are shown in the Year 17 Report. The URI Utilities Dept conducted the surveys and the testing was performed by ESS Labs.

IV.B.3.b.7

Use the space below to provide a description of efforts and actions taken as a result of for coordinating with other physically interconnected MS4s, including State and federal owned or operated MS4s, when illicit discharges were detected or reported. Identify person(s) / Department and/or parties responsible for the implementation of this requirement. Evaluate effectiveness of the implementation of this requirement.

During 2016 the University did not have any issues with illicit discharges associated with other MS4's. The only interconnections with another MS4 are two drainage lines that connect 12 catch basins from the South Kingston MS4 to the URI drainage system. Since there are rather limited interconnections, the University has not encountered any illicit discharges from other MS4's to date.

ILLICIT DISCHARGE DETECTION AND ELIMINATION cont'd

IV.B.3.b.8 Use the space below to provide a description of efforts and actions taken for the referral to RIDEM of non-stormwater discharges not authorized in accordance to Part I.B.3 of this permit or another appropriate RIPDES permit, which the operator has deemed appropriate to continue discharging to the MS4, for consideration of an appropriate permit. Identify person(s) / Department and/or parties responsible for the implementation of this requirement. Evaluate effectiveness of the implementation of this requirement.

The one illicit discharge that was not resolved at the end of 2015 was addressed in 2016. The Tootell Gym mechanical room sump pump which previously discharged directly into Ellery Pond has now been re-routed into the sanitary sewer system. The sump pump discharge included pool water backflows. The re-design of the sump pump discharge was performed by Gordon Archibald Associates and a contractor completed the work in September 2016.

IV.B.3.b.9

Use the space below to provide a description of efforts and actions taken to inform public employees, businesses, and the general public of hazards associated with illegal discharges and improper disposal of waste, as well as allowable non-stormwater discharges identified as significant contributors of pollutants. Include a description on how this activity was coordinated with the public education minimum measure and the pollution prevention/good housekeeping minimum measure programs. Identify person(s) / Department and/or parties responsible for the implementation of this requirement. Evaluate effectiveness of the implementation of this requirement.

All of the University's Facility Services personnel must attend annual training on identifying the materials that the employees are exposed, spill prevention plans, spill control procedures and the proper means of material disposal. The University's Safety & Risk Dept. conducts numerous trainings throughout the year in proper disposal of wastes and especially hazardous wastes. All employees working with the waste stream are required to attend re-fresher courses. The Safety and Risk Dept. added another module to their training program to reinforce the fact that dumping anything down a storm drain is a violation of the law and employees could face disciplinary action if they ignore this requirement. Staff employees have been trained to comply with spill control procedures and the proper disposal of waste. A campus wide effort to inform students, staff and visitors was implemented.

All contractors working on campus are required per contract to properly dispose of all waste material and are allowed only permitted discharges into the storm drainage system.

The University's Utilities Dept, The Safety and Risk Dept. and the Office of Capital Projects are tasked to monitor this requirement.

SECTION II.A Other Reporting Requirements - Illicit Discharge Investigation and System Mapping (Part IV.G.2.m)

14.0.2.111)	
# of Illicit Discharges Identified in 2016: 0	# of Illicit Discharges Tracked in 2016: 1
# of Illicit Discharges Eliminated in 2016: 1	# of Complaints Received: 0
# of Complaints Investigated: 0	# of Violations Issued: 0
# of Violations Resolved: 0	# of Unresolved Violations Referred to RIDEM: 0
Total # of Illicit Discharges Identified to Date (since 2003): 8	Total # of Illicit Discharges remaining unresolved at the end of 2016: 0

Summary of Enforcement Actions:

The university re-piped the sump discharge from the mechanical room of the Tootell Gym. The sump can collect some of the pool overflow. Previously the pool sump pump discharged into a storm drainage line that flows into Ellery Pond. The University procured the services of a Gordon R Archibald for the re-design the discharge of this sump to the sanitary sewer system.

Extent to which the MS4 sys	stem has been mapped:
-----------------------------	-----------------------

Total # of Outfalls Identified and Mapped to date: 98

ILLICIT DISCHARGE DETECTION AND ELIMINATION cont'd

Interconnection:	Date Found:	Location:	Name of Connectee:	Originating Source:	Planned and Coordinated Efforts and Activities with Connectee:
24" Storm Drain	2-8-11	Briar Lane	South Kingston	Wetlands south of Briar Lane	Agreed to notify SK Engineer of any issues
12" Storm Drain	2-8-11	Fortin Road	South Kingston	2 Catch Basins on Fortin Road	Agreed to notify SK Engineer of any issues
12" Storm Drain	2-8-11	Chapel Road	South Kingston	10 Catch Basins on Chapel Road	Agreed to notify SK Engineer of any issues



MINIMUM CONTROL MEASURE #4: CONSTRUCTION SITE STORMWATER RUNOFF CONTROL (Part IV.B.4 General Permit)

SECTION I. OVERALL EVALUATION:

GENERAL SUMMARY, STATUS, APPROPRIATENESS AND EFFECTIVENESS OF MEASURABLE GOALS:

Include information relevant to the implementation of each measurable goal, such as activities implemented to support the review, issuance and tracking of permits, inspections and receipt of complaints. Discuss activities to be carried out during the next reporting cycle. If addressing TMDL requirements, please indicate rationale for the activities chosen to address the pollutant of concern.

(Note: Identify parties responsible for achieving the measurable goals and reference any reliance on another entity for achieving measurable goals. Mark with an asterisk (*) if this person/entity is different from last year.) Responsible Party Contact Name: Andy Alcusky Phone: (401) 874-2448 Email: aalcusky@uri.edu IV.B.4.b.1 Indicate if the Sediment and Erosion Control and Control of Other Wastes at Construction Sites ordinance was not developed, adopted, and submitted to RIDEM, explain reasons why, submit proposed schedule for completion and identify person(s) / Department and/or parties responsible for the completion of this requirement. Date of Adoption: _N/A If the Ordinance was amended in 2016, please indicate why changes were necessary. Please also indicate if amendments have been made based on the 2010 RI Stormwater Design and Installation Standards Manual, and provide references to the amended portions of the local codes/ordinances. An ordinance for Sediment and Erosion Control and Control of Other Wastes at Construction Sites ordinance was not developed. The University does not have a mechanism to develop ordinances. The University owns all of the subject area and controls all activities on its properties. The mechanism to ensure proper erosion and sediment controls and control of other wastes is our "General Plans and Specifications" developed for and under the direction of the Office of Capital Projects

developed. The University does not have a mechanism to develop ordinances. The University owns all of the subject area and controls all activities on its properties. The mechanism to ensure proper erosion and sediment controls and control of other wastes is our "General Plans and Specifications" developed for and under the direction of the Office of Capital Projects by an A/E firm. Under Division 2, Site Construction, we require erosion and sediment control as well as the control of other wastes. These requirements are site specific and are developed by the A/E firm for each project. The requirements are enforced and managed by the project manager of each construction project. If the requirements are not met, we impose corrective actions in order to bring the project back into compliance. Failure to comply with the contract requirements results in a breach of contract and is dealt with according to contract law.

IV.B.4.b.6 Use the space below to describe actions taken as a result of receipt and consideration of information submitted by the public.

Information from the public would be documented and evaluated by the University with a response provided after the evaluation. In 2016 the University did not receive any information or requests for information from the public.

IV.B.4.b.8

Use the space below to describe activities and actions taken as a result of referring to the State non-compliant construction site operators. The operator may rely on the Department for assistance in enforcing the provisions of the RIPDES General Permit for Stormwater Discharges Associated with Construction Activity to the MS4 if the operator of the construction site fails to comply with the local and State requirements of the permit and the non-compliance results or has the potential to result in significant adverse environmental

The University did not have any referrals to the State for assistance in enforcing any part of RIPDES General Permit for Storm Water Discharge Associated with Construction Activity to this MS4 in 2016.

Additional Measurable Goals and Activities

CONSTRUCTION SITE STORMWATER RUNOFF CONTROL cont'd

SECTION II. A - Plan and SWPPP/SESC Plan Reviews during Year 13 (2016), Part IV.B.4.b.2: Issuance of permits and/or implementation of policies and procedures for all construction projects resulting in land disturbance of greater than 1 acre. **Part IV.B.4.b.4:** Review 100% of plans and SWPPPs/SESC Plans for construction projects resulting in land disturbance of 1-5 acres must be conducted by adequately trained personnel and incorporate consideration of potential water quality impacts.

of Construction Applications Received:5
of Construction Reviews Completed:2
of Permits/Authorizations Issued:2
Summary of Reviews and Findings, include an evaluation of the effectiveness of the program. Identify person(s) /Department and/or parties responsible for the implementation of this requirement.
Reviews were conducted and permits were issued for the Tootell Road Improvements and the Washburn parking Lot Modifications.
The application process was started for the new Engineering Complex, the Brookside Residence Hall and the Gateway Visitors Center. At the end of 2016 none of these projects had permits issued.
In all cases the applications were developed by an outside Engineering firm through the University's Capital Projects group.

SECTION II.B - Erosion and Sediment Control Inspections during Year 13 (2016), Parts IV.G.2.n and IV.B.4.b.7: Inspection of 100% of all construction projects within the regulated area that discharge or have the potential to discharge to the MS4 (the program must include two inspections of all construction sites, first inspection to be conducted during construction for compliance of the Erosion and Sediment controls at the site, the second to be conducted after the final stabilization of the site).

# of Active Construction Projects: 4		
# of Site Inspections: 4	# of Complaints Received: 0	
# of Violations Issued: 0	# of Unresolved Violations Referred to RIDEM: 0	

Summary of Enforcement Actions, include an evaluation of the effectiveness of the program. Identify person(s) /Department and/or parties responsible for the implementation of this requirement.

Final inspections were conducted by URI Utilities Dept. personnel at the new Chemistry Building, Tootell Road Improvements, Washburn Parking Lot Modifications and the Ranger Hall Renovations.

Our records do not indicate any un-resolved complaints at any of these projects.



MINIMUM CONTROL MEASURE #5: POST CONSTRUCTION STORMWATER MANAGEMENT IN NEW DEVELOPMENT AND **REVELOPMENT**

(Part IV.B.5 General Permit)

SECTION I. OVERALL EVALUATION:

GENERAL SUMMARY, STATUS, APPROPRIATENESS AND EFFECTIVENESS OF MEASURABLE GOALS:

Include information relevant to the implementation of each measurable goal, such as activities implemented to support the

incorporated th	ce and tracking of permits, inspections and receipt of complaints, etc. Please indicate if any projects have ne use of Low Impact Development techniques. Discuss activities to be carried out during the next reporting ssing TMDL requirements, please indicate rationale for the activities chosen to address the pollutant of
	parties responsible for achieving the measurable goals and reference any reliance on another entity measurable goals. Mark with an asterisk (*) if this person/entity is different from last year.)
Responsible I	Party Contact Name: Andy Alcusky
Phone: (401) 8	B74-2448 Email: aalcusky@uri.edu
IV.B.5.b.5	Use the space below to describe activities and actions taken to coordinate with existing State programs requiring post-construction stormwater management.
	P maintenance schedules are required to be included as part of the approval process for new development. chedules are developed in accordance to the Rhode Island Stormwater design and Installation Standards
IV.B.5.b.6	Use the space below to describe actions taken for the referral to RIDEM of new discharges of stormwater associated with industrial activity as defined in RIPDES Rule 31(b)(15) (the operator must implement procedures to identify new activities that require permitting, notify RIDEM, and refer facilities with new stormwater discharges associated with industrial activity to ensure that facilities will obtain the proper permits).
	any new industrial activity at this MS4 in 20016. Therefore there were no referrals to the State for any new storm water associated with industrial activity.
IV.B.5.b.9	Indicate if the Post-Construction Runoff from New Development and Redevelopment Ordinance was not developed, adopted, and submitted to RIDEM, explain reasons why, submit proposed schedule for completion and identify person(s) / Department and/or parties responsible for the completion of this requirement. Date of Adoption: If the Ordinance was amended in 2016, please indicate why changes were necessary. Please also indicate if amendments have been made based on the 2010 RI Stormwater Design and Installation Standards Manual, and provide references to the amended portions of the local codes/ordinances.
does not have property. The reconstruction is Projects by an other wastes. the A/E firm. Twith our own country according to construction of the country according to construct the construction according to construct the construct the construction according to the construction according to construct the construction according to the construction according to the construction according to the construction	
IV.B.5.b.12	Use the space below to describe activities and actions taken to identify existing stormwater structural BMPs discharging to the MS4 with a goal of ensuring long term O&M of the BMPs.
BMPs since th during new cor each new BMF increased and	was formulated in the Drainage Master Plan of 2006. In 2008, the list of BMPs was updated to include new e Master Drainage Plan was developed. The procedure to add new BMPs and delete the BMP's removed instruction is an annual task for the Utilities Dept. The Utilities Dept. updates the maintenance requirements for P. Each year the University updates this list as new work is completed on campus. In 2016 the number of BMP's the updated list is included with the report. The BMP list increased due to a number of projects completed in The University uses the BMP list to schedule BMP maintenance.

Additional Measurable Goals and Activities

SECTION II.A Plan and SWPPP/SESC Plan Reviews during Year 13 (2016), Part IV.B.5.b.4: Review 100% of po	st-
construction BMPs for the control of stormwater runoff from new development and redevelopment projects that result in discharge	es:
to the MS4 which incorporates consideration of potential water quality impacts (the program requires reviewing 100% of plans for	
development projects greater than 1 acre, not reviewed by other State programs).	
# of Post-Construction Applications Received: 0	1

of Post-Construction Applications Received:0
of Post-Construction Reviews Completed:0
of Permits/Authorizations Issued:0
Summary of Reviews and Finding, include an evaluation of the effectiveness of the program. Identify person(s) /Department and/or parties responsible for the implementation of this requirement.
There was no new development in 2016 that would require the plan reviews. All of the URI projects are reviewed by other state programs.

SECTION II.B. - Post Construction Inspections during Year 13 (2016), Parts IV.G.2.o and IV.B.5.b.10 - Proper Installation of Structural BMPs: Inspection of BMPs, to ensure these are constructed in accordance with the approved plans (the program must include inspection of 100% of all development greater than one acre within the regulated areas that result in discharges to the MS4 regardless of whom performs the review).

# of Active Construction Projects: 4	# of Construction Projects Completed: 4		
# of Site Inspections for proper Installation of BMPs: 4	# of Complaints Received: 0		
# of Violations Issued: 0	# of Unresolved Violations Referred to RIDEM: 0		
Summary of Enforcement Actions:			

No enforcement actions were required. The URI Utilities Dept. conducted post construction inspections of four new BMP's at the new Chemistry Building, one new BMP at Ranger Hall, and three BMP's installed by URI's Lands and Grounds Dept. south of the Elephant Walk.

SECTION II.C. - Post Construction Inspections during Year 13 (2016), Parts IV.G.2.p and IV.B.5.b.11 - Proper Operation and Maintenance of Structural BMPs: Describe activities and actions taken to track required Operations and Maintenance (O&M) actions for site inspections and enforcement of the O&M of structural BMPs. Tracking of required O&M actions for site inspections and enforcement of the O&M of structural BMPs.

# of Site Inspections for proper O&M of BMPs: 107	# of Complaints Received: 0	
# of Violations Issued: 0	# of Unresolved Violations Referred to RIDEM: 0	

Summary of Activities and Enforcement Actions. Evaluate the effectiveness of the Program in minimizing water quality impacts. Identify person(s) /Department and/or parties responsible for the implementation of this requirement.

The Utilities Dept. conducted inspections of all structural BMP's throughout the campus. A total of 45 work orders were issued to the Lands & Grounds Dept. for maintenance. The inspections provide a good mechanism to identify potential problems (such as flooding risks to buildings) in addition to the environmental concerns. When the work orders are completed the Utilities Dept. Work orders then verifies the work was properly completed.

POST CONSTRUCTION STORMWATER MANAGEMENT IN NEW DEVELOPMENT AND REDEVELOPMENT cont'd

Strategies being implemented to ensure long-term Operation and Maintenance (O&M) of priv BMPs, check all that apply in your municipality/MS4:	ately-owned st	ormwater
None, No privately owned BMP's.		
☐ Ordinances or by-laws identify BMP inspection responsible party		
☐ Ordinances or by-laws identify BMP maintenance responsible party		
☐ Ordinances or by-laws identify BMP inspections and maintenance requirements		
☐ Ordinances or by-laws provide for easements or covenants for inspections and maintenance		
☐ Ordinances or by-laws require for every constructed BMP an inspections and maintenance agre	ement	
☐ Ordinances or by-laws contain requirements for documenting and detailing inspections		
☐ Ordinances or by-laws contain requirements for documenting and detailing maintenance		
☐ Ordinances or by-laws contain authority to enforce for lack of maintenance or BMP failure		
☐ The MS4 is responsible for inspections of all privately-owned BMPs		
☐ The MS4 is responsible for maintenance of all privately-owned BMPs		
☐ Establishment of escrow account for use in case of failure of BMP		
☐ Other strategies to ensure long-term O&M of privately-owned BMPs, describe:		
The University does not have any privately owned BMP's. All BMP's are MS4 owned BMP's.		
Does your municipality/MS4 require the use BMPs Operations and Maintenance Agreements?	□ YES	X N/A
If YES, please indicate if the Operations and Maintenance Agreements include the following:		
a. Party responsible for the long-term O&M of permanent stormwater management BMPs	☐ YES	X N/A
b. A description of the permanent stormwater BMPs that will be operated and maintained	☐ YES	X N/A
 c. The location of the permanent stormwater BMPs that will be operated and maintained d. A timeframe for routine and emergency inspections and maintenance of all permanent 	☐ YES	X N/A
stormwater management BMPs	☐ YES	X N/A
e. A requirement that all inspections and maintenance activities are documented	☐ YES	X N/A
f. Annual submission of inspection/maintenance certification/documentation to the MS4	☐ YES	X N/A
g. Stormwater management easement for access for inspections and maintenance or the preservation of stormwater runoff conveyance, infiltration, and detention areas and other stormwater controls and BMPs by persons other than the property owner	☐ YES	X N/A
h. Steps available for addressing a failure to maintain the stormwater controls and BMPs	□ YES	X N/A
Please elaborate, if appropriate:		The state of the s
Does your municipality/MS4 keep an inventory of privately-owned BMPs?	□ YES	NO NO
		<u>M</u> 110
For privately-owned BMPs, does your municipality/MS4 have a system for tracking:		<u>₩</u>
a. Agreements and arrangements to ensure O&M of BMPs? b. Inspections?	☐ YES	X N/A X N/A
c. Maintenance and schedules?	☐ YES ☐ YES	X N/A X N/A
d. Complaints?	□ YES	X N/A
e. Non-Compliance?	□ YES	X N/A
f. Enforcement actions?	□ YES	X N/A
Do you use an electronic tool (e.g. GIS, database, spreadsheet) to track post-construction BMPs, in maintenance? YES If yes, please elaborate on which tools are used:	spections, and N/A	
NOTE: BMP maintenance tasks can be a great way to involve and educate the community to their p have the potential to create a highly interactive environment for community members and volunteer .		



MINIMUM CONTROL MEASURE #6: POLLUTION PREVENTION AND GOOD HOUSEKEEPING IN MUNICIPAL OPERATIONS (Part IV.B.6 General Permit)

SECTION I. OVERALL EVALUATION:

ECTION I. OVERALE EVALUATION.				
GENERAL SUMMARY, STATUS, APPROPRIATENESS AND EFFECTIVENESS OF MEASURABLE GOALS:				
Include information relevant to the implementation of each measurable goal, such as activities and practices used to address on-going requirements, and personnel responsible. Discuss activities to be carried out during the next reporting cycle. If addressing TMDL requirements, please indicate rationale for the activities chosen to address the pollutant of concern.				
	y parties responsible for achieving the measurable goals and reference any reliance on another entity for asurable goals. Mark with an asterisk (*) if this person/entity is different from last year.)			
Responsible I	Party Contact Name: Andy Alcusky			
Phone: (401)	874-2448Email: aalcusky@uri.edu			
IV.B.6.b.1.i	Use the space below to describe activities and actions taken to identify structural BMPs owned or operated by the small MS4 operator (the program must include identification and listing of the specific location and a description of all structural BMPs in the SWMPP and update the information in the Annual Report). Evaluate appropriateness and effectiveness of this requirement.			
	Do you have an inventory of MS4-owned/operated BMPs? ☐ YES ☐ NO			
	Total # of MS4-owned/operated BMPs (does not include CBs or MHs): 107			
The University updates the list of BMP's annually. BMP's are added/removed as a result of new construction activity. In addition the BMP list expanded as a result of the updated Campus Master Drainage Plan. The BMP list is also updated as a result of various other stormwater inspections such as catch basin and outfall inspections. Other BMP's are discovered during storm events when we observe storm water flow throughout the campus. In 2016, eleven new BMP's were added to our inventory of BMP's. The eleven new BMP's are a result of recent construction work, in-house modifications by our Lands and Grounds Dept. and further review of the University's drainage system The University's Utilities Dept. uses this inventory for planned inspections/maintenance of the BMP's. The BMP inventory list is a useful tool to ensure proper inspection of all BMP's.				
IV.B.6.b.1.ii	Use the space below to describe activities and actions taken for inspections, cleaning and repair of detention/retention basins, storm sewers and catch basins with appropriate scheduling given intensity and type of use in the catchment area. Evaluate appropriateness and effectiveness of this requirement.			
	# of MS4-owned/operated BMPs inspected in 2016:114			
	# of MS4-owned/operated BMPs maintained/cleaned in 2016: 45			
	# of MS4-owned/operated BMPs repaired in 2016:1			
	Does your municipality/MS4 have a system for tracking:			
	a. Inspection schedules of MS4-owned BMPs? b. Maintenance/cleaning schedules of MS4-owned BMPs? C. Repairs, corrective actions needed? X YES □ NO NO NO			
	b. Maintenance/cleaning schedules of MS4-owned BMPs? X YES			
	c. Repairs, corrective actions needed?			
	d. Complaints? ☐ NO			
	Do you use an electronic tool (e.g. GIS, database, spreadsheet) to track stormwater BMPs, inspections, and maintenance?			
The University's BMP inventory spreadsheet lists the inspection and maintenance requirements for each BMP. Results of the				
inspections and any maintenance /corrective actions taken are included in an expanded portion of the BMP inventory spreadsheet. The expanded inventory spreadsheet noted 45 BMP's that required maintenance with most of them requiring a				
cleaning. The BMP repaired was the CBLS rain garden and required replacing a section of plugged under drain.				

	POLLUTION PREVENTION AND GOOD HOUSEKEEPING IN MUNICIPAL OPERATIONS cont				
IV.B.6.b.1.iii	Use the space below to describe activities and actions taken to support the requirement of yearly inspection and cleaning of all catch basins (a lesser frequency of inspection based on at least two consecutive years of operational data indicating the system does not require annual cleaning might be acceptable). Evaluate appropriateness and effectiveness of this requirement.				
	Total # of CBs within regulated area (including SRPW and TMDL areas): 897				
	# of CBs inspected in 2016: <u>891</u>				
	# of CBs cleaned in 2016: <u>543</u> % of Total cleaned: <u>60 % of all CB's 79% of CB's with sumps</u>				
	Quantity of sand/debris collected by cleaning of catch basins: 35 loads; 3CY/Load = 105 CY				
	Location used for the disposal of debris: On university property at soil stockpile compost area				
	Do you use an electronic tool (e.g. GIS, database, spreadsheet) to track the inspections and cleaning of catch basins?				
structures. Generally the catch basins along all roads are cleaned yearly. These basins generally need annual cleanings due mainly to the amount of leaves that flow into the basins. Basins located in turf areas usually do not require the annual cleanings but are inspected annually. Basins in turf areas are usually cleaned at longer intervals. Cleaning some of the basins in turf areas could result in damages resulting from truck access to the area so cleaning of these basins is performed sporadically.					
IV.B.6.b.1.iv	IV.B.6.b.1.iv Use the space below to describe activities and actions taken to minimize erosion of road shoulders and roadside ditches by requiring stabilization of those areas. Evaluate appropriateness and effectiveness of this				
campus. Additional Impl Additi Road west of the su A considew	niversity worked in a number of areas to minimize erosion of road shoulders and sloped areas throughout the rovements included the following: ional curbing and sidewalks were installed on the north side of West Alumni Ave and east side of Butterfield I in the vicinity of the new electrical sub-stations. The curbing was installed to limit erosion from water flowing down West Alumni Ave and then cutting across the new sub-station site and eroding a slope on the west side of ub-station site. Sidewalks were installed in place of muddy paths to limit erosion caused by foot traffic. Intractor working for the URI Lands and Grounds Dept. replaced sections of sidewalk along Flagg Road. The new walks were installed approximately 10 feet back from the curb line. The sidewalk re-location limits damage down dewalk plows in the winter. When the sidewalk abuts the curb the sidewalk plows tend to plow past the sidewalk				

Most roadways throughout campus have curbs to minimize erosion. Swales and ditches are also used to limit erosion of road side shoulders. Areas that have been disturbed by winter activities are repaired and seeded in the spring. The University has been making a concerted effort to funnel pedestrian traffic to remain on walkways and have been trying to restrict pedestrian traffic from shortcuts across landscaped areas. Other areas that could be subject to erosion are being identified to be addressed in 2017.

IV.B.6.b.1.v

Use the space below to describe activities and actions taken to identify and report known discharges causing scouring at outfall pipes or outfalls with excessive sedimentation, for the Department to determine on a caseby-case basis if the scouring or sedimentation is a significant and continuous source of sediments. Evaluate appropriateness and effectiveness of this requirement.

During the annual inspection of outfalls, the outfalls are inspected for scouring and excessive sedimentation. Areas that are in need of repair are reported to the URI Control Center and a work order is generated.

There were ten outfalls identified in 2016 where there was moderate sedimentation. These outfalls were cleaned up by the URI Lands & Grounds Dept.

The inspections of the outfalls are not only a requirement but provide a tremendous tool to identify potential storm water flow issues prior to a significant rain event.

IV.B.6.b.1.vi	Use the space below to indicate if all streets and roads within the urbanized area were swept annually and if not indicate reason(s). Evaluate appropriateness and effectiveness of this requirement.				
	Total roadway miles within regulated area (including SRPW and TMDL areas): _7				
	Roadway miles that were swept in 2016: _7 % of Total swept: _100%				
	Type of sweeper used: X Rotary brush street sweeper X Vacuum street sweeper				
	Quantity of sand/debris collected by sweeping of streets and roads: 250 CF				
	Location used for the disposal of debris Soil stockpile site on University Property				
	Do you use an electronic tool (e.g. GIS, database, spreadsheet) to track the annual sweeping of streets and roads?				
A tracking tool is not required since all roadways and most parking lots are swept each spring to remove sand and sediment as a result of winter storms. Parking lots not swept such as porous pavement parking lots are vacuumed. Additional sweeping of roads also occurs just prior to commencement activities in May as well as needed throughout the year. The work is required not only for runoff concerns but as well as safety issues with bicycles and other modes of transport across campus and for general aesthetics. In the summer the gutters along the campus roads are vacuumed monthly to remove accumulated debris. In the fall the gutters along the roads are vacuumed weekly (October & November) to remove accumulated leaves and debris. The sweeping of the roads is performed by outside contractors under the direction of the Lands and Ground Dept. The University uses only a limited amount of sand during the winter months. The URI Lands and Grounds Dept. is responsible for vacuuming the gutters.					
IV.B.6.b.1.vii	Use the space below to describe activities and actions taken for controls to reduce floatables and other pollutants from the MS4. Evaluate appropriateness and effectiveness of this requirement.				
The vast majority of the floatables encountered was trash. During 2016 the University has continued staffing part time workers in the trash and recycling crews in order to provide trash and recycling coverage seven days per week. Locations of trash and recycling bins have increased and locations changed to better suit the foot traffic. Trash and recycle bins are emptied daily during the week. Local building superintendents and custodian staff have been instructed to call the Control center if they see a trash or recycle container full. A number of community events were scheduled to reduce trash throughout the campus. Events included a Fraternity Circle cleanup event and earth day cleanups. Each event had approximately 75 people in attendance.					
IV.B.6.b.1.viii	Use the space below to describe the method for disposal of waste removed from MS4s and waste from other municipal operations, including accumulated sediments, floatables and other debris and methods for record-keeping and tracking of this information.				
	Do you have a system for tracking actions to remove and dispose of waste?				
Sediments removed from drainage structures and ponds (if tests indicate that they are acceptable) are re-used for fill projects throughout the campus. Trash and recyclable materials are trucked off campus. The URI Lands and Grounds Dept. and Utilities Dept. are responsible for this activity. Presently the amount of waste has not been estimated. Sediment waste is estimated by the quantity of full truckloads of sediment removed. URI has not developed a means to track the sediment removed from each drainage structure. Floatables are removed on a regular basis from waterways and adjacent areas, but quantities are not kept.					
	Use the space below to describe and indicate activities and corrective actions for the evaluation of compliance. This evaluation must include visual quarterly monitoring; routine visual inspections of designated equipment, processes, and material handling areas for evidence of, or the potential for, pollutants entering the drainage system or point source discharges to a waters of the State; and inspection of the entire facility at least once a year for evidence of pollution, evaluation of BMPs that have been implemented, and inspection of equipment. A Compliance Evaluation report summarizing the scope of the inspection, personnel making the inspection, major observations related to the implementation of the Stormwater Management Plan (formerly known as a Stormwater Pollution Prevention Plan), and any actions taken to amend the Plan must be kept for tilities Dept. conducted quarterly monitoring and routing inspections of the URI Facilities Areas in 2016. A full				
inspection of the Facilities Services area of the campus was also performed and is documented in the evaluation report. URI has a SPCC Plan in place. This Facilities Area is monitored on a regular basis and routine walkthroughs occur at least once a month. If any issues are noted a work order will be generated.					

IV.B.6.b.6	Use the space below to describe all employee training programs used to prevent and reduce stormwater pollution from activities such as park and open space maintenance, fleet and building maintenance, new construction and land disturbances, and stormwater system maintenance for the past calendar year, including staff municipal participation in the URI NEMO stormwater public education and outreach program and all inhouse training conducted by municipality or other parties. Evaluate appropriateness and effectiveness of this requirement.			
	How many stormwater management trainings have been provided to <i>municipal employees</i> during this reporting period?3			
	What was the date of the last training? <u>12 / 08 / 16</u>			
	How many municipal employees have been trained in this reporting period? _200_			
	What percent of <i>municipal employees</i> in relevant positions and departments received stormwater management training? <u>100</u> %			
These courses The annual ref the regulations of some of the manner. As a r waste products	requires the Facilities Dept staff to attend refresher courses on material handling and proper disposal annually. It is are conducted by the URI Safety and Risk Dept. The staff, is needed not only per regulations, but it is a useful tool to reinforce the reasons why is are required. Attendees of the material handling safety course have noted some potential issues with disposal in cleaning products. The custodial staff had noted the difficulty emptying their waxing machines in the proper result of the safety sessions the University's Safety and Risk Dept is working with the custodial staff to ensure the staff are not discharged into the storm water system. The training program has also eliminated potential illicit			
discharges into	the storm water system.			
IV.B.6.b.7	Use the space below to describe actions taken to ensure that new flow management projects undertaken by the operator are assessed for potential water quality impacts and existing projects are assessed for incorporation of additional water quality protection devices or practices. Evaluate appropriateness and effectiveness of this requirement.			
infiltration and standards. In a detention/infiltr amount of eros	ting is required for all new flow management projects to assess water quality impacts. The University encourages groundwater recharge utilization in new projects and re-developments in addition to complying with regulatory addition to the large scale permitted projects, the University has been installing a number of small ration basins, grass swales and berms to capture storm water flow. These small projects significantly reduce the sion and sedimentation issues downstream. In 2016 three small basins were built by the University's Lands and adjacent to the Elephant Walk. We expect to address other areas on campus in 2017.			
Additional Mea	asurable Goals and Activities			

SECTION II.A - Structural BMPs (Part IV.B.6.b.1.i)

BMP ID:	Location:	Name of BMP Owner/Operator:	Description of BMP:	Frequency of Inspection:
BMP-01	Northwest of Independence Square and	URI	Level Spreader	Review Annually
BMP-02	Ballentine Hall Detention Pond, north of Ballentine	URI	Detention Pond	Inspect Twice per Year
BMP-03	Butterfield Rd Sedimentation box; North	URI	Sedimentation Box	Inspect Annually
BMP-04	CBLS Rain Garden	URI	Rain Garden	Inspect Annually
BMP-05	North of CHI PHI Fraternity House, NW of	URI	Detention structure, Stormceptor	Inspect Annually
BMP-06	BMP removed	URI	Detention Area removed as part of	N/A
BMP-07	Culvert at Route 138 Crossing White Horn	URI	Culvert	Inspect Twice per Year
BMP-08	White Horn Brook Culvert at Fraternity Circle	URI	Culvert	Inspect Twice per Year
BMP-09	White Horn Brook Culvert at Fraternity Circle	URI	Culvert	Inspect Twice per Year
BMP-10	White Horn Brook Culvert East of Mackal Gym	URI	Culvert	Inspect Twice per Year
BMP-11	White Horn Brook Culvert at Elephant Walk	URI	Culvert	Inspect Twice per Year
BMP-12	White Horn Brook Culvert West of Dorr Hall	URI	Culvert	Inspect Twice per Year
BMP-13	White Horn Brook Culvert West Alumni Avenue	URI	Culvert	Inspect Twice per Year
BMP-14	White Horn Brook Culvert at Flagg Road	URI	Culvert	Inspect Twice per Year
BMP-15	Culvert Crossing Plains Road just South of Central	URI	Culvert	Inspect Twice per Year
BMP-16	Dairy Barn Parking Lot; North of Meade Stadium	URI	Pervious Parking Surface	Inspect Twice per Year
BMP-17	Eddy Hall Infiltration System	URI	Infiltration System for Roof Drainage	Inspect Annually
BMP-18	Ellery Pond	URI	Detention Pond	Inspect Twice per Year
BMP-19	Flagg Road Parking Lot West detention Basin	URI	Detention Pond	Inspect Twice per Year
BMP-20	Flagg Road Parking Lot East Detention Basin	URI	Detention Pond	Inspect Twice per Year
BMP-21	Swale East of Heathman Road	URI	Swale	Inspect Twice per Year
BMP-22	Merrow Hall Detention Area West of Merrow Hall	URI	Detention Pond	Inspect Annually
BMP-23	Plains Road Parking Lot	URI	Swales, Infiltration System	Inspect Twice per Year
BMP-24	Plains Road Parking Lot	URI	Pervious Parking Surface	Inspect Twice per Year
BMP-25	Ryan Center/Tootell Vortechnics Units	URI	Vortechnics	Inspect Annually
BMP-26	Swale North of Sherman Building	URI	Swale	Inspect Twice per Year
BMP-27	Fraternity Circle Swale – North of Sigma Chi	URI	Swale	Inspect Twice per Year
BMP-28	White Horn Brook	URI	Stream/drainage Conduit	Inspect Twice per Year

1		THOM AND GOOD HOUSE		7.12 07 27.17.17.107.10 007.11
BMP-29	Infiltration Systems at Wiley/Garrahy Halls	URI	Infiltration Systems	Inspect Annually
BMP-30	Hope Dining Hall Drainage	URI	CB/DMH & Piping Drainage system	Inspect Annually
BMP-31	Freshman Dorms Drainage System	URI	CB/DMH & Piping Drainage System	Inspect Annually
BMP-32	Wiley/Garrahy Drainage System	URI	CB/DMH & Piping Drainage System	Inspect Annually
BMP-33	Eddy Hall Drainage System	URI	CB/DMH & Piping Drainage System	Inspect Annually
BMP-34	Flagg Road Swale (North of Flagg Road)	URI	Swale	Inspect Twice per Year
BMP-35	Plains Road Parking Lot Drainage	URI	Drainage System	Inspect Annually
BMP-36	Campus Wide Catch Basins	URI	Drainage System	Inspect Annually
BMP-37	Campus Wide DMH's	URI	Drainage System	Inspect Annually
BMP-38	Campus Wide Street Sweeping	URI	Street Sweeping	Inspect Annually
BMP-39	Campus Wide Parking Lots Sweeping	URI	Parking Lot Sweeping	Inspect Annually
BMP-40	Flagg Road/Plains Road Catch Basins	URI	Drainage System	Inspect Annually
BMP-41	Coastal Institute Catch Basins	URI	Drainage System	Inspect Annually
BMP-42	Campus Wide Streets and Walkways	URI	Inspect on a regular basis for potential	Inspect Annually
BMP-43	Campus Wide Outfalls	URI	Outfalls	Inspect Annually
BMP-44	Outfall Map	URI	Outfall Map	Inspect Annually
BMP-45	Independence Square Infiltration System	URI	Infiltration System	Inspect Annually
BMP-46	Roger Williams Detention Pond	URI	Detention Pond	Inspect Twice per Year
BMP-47	Open Channel North of Hope Dining Hall	URI	Waterway	Inspect Twice per Year
BMP-48	Open Channel South of Hutchinson Hall	URI	Waterway	Inspect Twice per Year
BMP-49	Retaining Wall South of CBLS	URI	BMP Removed in 2015 as Part of New	N/A
BMP-50	CBLS Green Roof	URI	Green roof	Inspect Twice per Year
BMP-51	CBLS Stormceptor	URI	Sedimentation unit	Inspect Twice per Year
BMP-52	Hillside Dorm Water Quality Structures	URI	Sedimentation Unit	Inspect Twice per Year
BMP-53	Hillside Dorms Bio- retention Areas	URI	Bio-retention area	Inspect Twice per Year
BMP-54	Infiltration Basin south of Baird Hill Road and West	URI	Infiltration Basin	Inspect Twice per Year
BMP-55	Bio-Retention Area North of College of Pharmacy	URI	Bio-Retention Area	Inspect Twice per Year
BMP-56	Swale south of Parking Services Building	URI	Swale	Inspect Twice per Year
BMP-57	Swale East of Hillside East Access Road	URI	Swale	Inspect Twice per Year
BMP-58	Paved swales at Keaney Parking Lot	URI	Swale	Inspect Twice per Year
			•	

	POLLUTION PREVE	NTION AND GOOD HOUS	ENEET HIS HIS MONICH	AL OI LIVATIONS COM
BMP-59	Sherman East Lot infiltration System	URI	Infiltration System	Inspect Twice per Year
BMP-60	Wellness Center Infiltration System	URI	Infiltration System	Inspect Twice per Year
BMP-61	Culverts Crossing Plains Road North of	URI	Culverts	Inspect Twice per Year
BMP-62	Culverts Crossing Flagg Road West of	URI	Culverts	Inspect Twice per Year
BMP-63	Flagg Road Extension Detention/Infiltration Basin	URI	Infiltration Systems	Inspect Twice per Year
BMP-64	Flagg Road Extension Porous Paving Lot	URI	Pervious Parking Surface	Inspect Twice per Year
BMP-65	Central Receiving Infiltration	URI	Infiltration System	Inspect Twice per Year
BMP-66	Storm Water Test Station	URI	Sampling Station	Inspect Annually
BMP-67	Infiltration/Detention Basin South of	URI	Infiltration System	Inspect Twice per Year
BMP-68	Swale East of Butterfield Hall	URI	Swale	Inspect Twice per Year
BMP-69	COP Medicinal Garden	URI	Rain Garden	Inspect Annually
BMP-70	Swale West of Davis Hall	URI	Swale	Inspect Twice per Year
BMP-71	Swale East of Rodman Hall	URI	Swale	Inspect Twice per Year
BMP-72	Swale East of White Hall (BMP	URI	Swale – Removed in 2014 as part of new	N/A
BMP-73	Swale South of Fayerweather Hall	URI	Swale	Inspect Twice per Year
BMP-74	Paved Swales at Gateway Apartments	URI	Swale	Inspect Annually
BMP-75	Paved Swale at Well House No. 2	URI	Swale	Inspect Twice per Year
BMP-76	Plains Lot Addition (2013) – Infiltration Channels	URI	Infiltration System	Inspect Twice per Year
BMP-77	Flagg Road Extension Swales Parallel to Road	URI	Swale	Inspect Twice per Year
BMP-78	Plains Lot Addition (2013) – New Culverts into Basin	URI	Culverts	Inspect Twice per Year
BMP-79	Flagg Road Extension – Paved Waterways	URI	Swale	Inspect Twice per Year
BMP-80	Flagg Road Extension Basin "H" Discharge	URI	Infiltration system	Inspect Twice per Year
BMP-81	White Hall Lot – Swale at NW Corner of Lot	URI	Swale	Inspect Twice per Year
BMP-82	Greenhouse Lot – Dry Swales	URI	Swale	Inspect Twice per Year
BMP-83	Greenhouse Lot – Grass Channel	URI	Swale	Inspect Twice per Year
BMP-84	Greenhouse Lot – Paved Waterways	URI	Swale	Inspect Twice per Year
BMP-85	Greenhouse Lot – Forebay/Infiltration	URI	Infiltration System	Inspect Twice per Year
BMP-86	Greenhouse Roof Drain infiltration System	URI	Infiltration System	Inspect Twice per Year
BMP-87	Hillside Dorm Green Roof	URI	Infiltration System	Review Annually
BMP-88	Flagg Road Detention Basin "D"	URI	Infiltration System	Review Annually

	TOLLOTTONT NEVEL	VIION AND GOOD HOUSE	INCLI ING IN MONION	AL OI LIVATIONS COIN
BMP-89	Flagg Road Detention Basin "E"	URI	Infiltration System	Review Annually
BMP-90	Flagg Road Detention Basin "H"	URI	Infiltration System	Review Annually
BMP-91	Stone Swale east of Butterfield Residence	URI	Swale	Review Annually
BMP-92	Tree Box Filters in Chemistry Building Area	URI	Detention/Infiltration System	Review Annually
BMP-93	Bioretention/Detention/ Forebay System North of New Chemistry	URI	Detention/Infiltration System	Review Annually
BMP-94	Bioretention/Detention/ Forebay System South of New Chemistry	URI	Detention/Infiltration System	Review Annually
BMP-95	Tree Box Filters in Flagg Road Parking Lot	URI	Detention/Infiltration System	Review Annually
BMP-96	Swale North of the CBLS NW Corner	URI	Swale	Review Annually
BMP-97	Rip Rap Swale West of New Electric Sub-	URI	Swale	Review Annually
BMP-98	Rip Rap Swale East of Butterfield Dining Hall	URI	Swale	Review Annually
BMP-99	Asphalt Berms at Fraternity Circle	URI	Swale	Review Annually
BMP-100	Swale North of Hopkins Hall	URI	Swale	Review Annually
BMP-101	Swale North of Chemistry/White Hall	URI	Swale	Review Annually
BMP-102	Detention Basin South of Elephant Walk 250'	URI	Detention	Review Annually
BMP-103	Detention Basin East of Butterfield Hall	URI	Detention	Review Annually
BMP-104	Detention Basin 100' East of Butterfield Hall	URI	Detention	Review Annually
BMP-105	Rip Rap Swale at SW corner of Chafee Hall	URI	Swale	Review Annually
BMP-106	Tootell Rd Drainage – Infiltration	URI	Infiltration	Review Annually
BMP-107	Browning Hall Infiltration System	URI	Infiltration	Review Annually
BMP-108	Weldin Hall Infiltration System	URI	Infiltration	Review Annually
BMP-109	Sigma Chi Infiltration System	URI	Infiltration	Review Annually
BMP-110	Int Institute of Sports Infiltration System	URI	Infiltration	Review Annually
BMP-111	Ryan Center Votechics (NE)	URI	Vortechnics	Review Annually
BMP-112	Swales SE and East of Ranger Hall	URI	Swale	Review Annually
BMP-113	Baseball Field Dry Wells	URI	Infiltration	Review Annually
BMP-114	Dry Well South of Green Hall	URI	Infiltration	Review Annually

Outfall ID:	Location:	Description of Problem:	Description of Remediation Taken, include dates:	Receiving Water Body Name/Description:
URI-001	Flagg Road at White Horn Brook	Sedimentation	Sedimentation removed by backhoe in August 2016	White Horn Brook
URI-002	SW of Heathman Hall	Sedimentation	Sedimentation removed by backhoe in August 2016	White Horn Brook
URI-016	SW of Fayerweather Hall	Sedimentation	Sedimentation removed by backhoe in August 2016	White Horn Brook
URI-029	Keaney Lot SE Corner at WH Brook	Sedimentation	Sedimentation removed by backhoe in August 2016	White Horn Brook
URI-049	Fine Arts Lot NW Corner	Sedimentation	Sedimentation removed by backhoe in August 2016	White Horn Brook
URI-064	Hillside Bio- Retention North	Sedimentation	Sedimentation removed by backhoe in August 2016	Ellery Pond

SECTION II.C - Note any planned municipal construction projects/opportunities to incorporate water quality BMPs, low impact development, or activities to promote infiltration and recharge (Part IV.G.2.j).

The design for the renovations to the fine Arts Parking Lot has been submitted and approved by DEM. The renovation to the Fine Arts Parking Lot will incorporate a number water quality features such as storage systems with metered outflow, bioretention basins and bioretention swales. This project was designed by Gordon R Archibald Associates and has been reviewed by DEM.

The new Engineering Complex will also incorporate a number of water quality BMP's including detention/infiltration system, rain gardens and Bio-Retention areas. The Brookside Apartments Project is also currently under design and will incorporate a number of water Quality BMP's such as Bio-Retention areas, tree filters, and grass swales.

SECTION II.D - Please include a summary of results of any other information that has been collected and analyzed. This includes any type of data (Part IV.G.2.e).

Dry weather survey date is attached to this report and has also been sent to DEM electronically.	



TOTAL MAXIMUM DAILY LOAD (TMDL) or other Water Quality Determination REQUIREMENTS

stormwater cor assessment of	you have been notifi ntrols based on an a f the progress towar DL (Part IV.G.2.d). Ple	approved TMDL or rds meeting the req	other water quality quirements for the	y determination, pl control of stormwa	lease provide an ater identified in the)



SPECIAL RESOURCE PROTECTION WATERS (SRPWs)

SECTION I. In accordance with Rule 31(a)(5)(i)G of the Regulations for the Rhode Island Pollutant Discharge Elimination System (RIPDES Regs), on or after March 10, 2008, any discharge from a small municipal separate storm sewer system to any Special Resource Protection Waters (SRPWs) or impaired water bodies within its jurisdiction must obtain permits if a waiver has not been granted in accordance to Rule 31(g)(5)(iii). A list of SRPWs can be found in Appendix D of the RIDEM Water Quality Regulations at this link: http://www.dem.ri.gov/pubs/regs/regs/water/h20q09a.pdf

The 2008 303(d) Impaired Waters list can be found in Appendix G of the 2008 Integrated Water Quality Monitoring and Assessment Report at this link: http://www.dem.ri.gov/programs/benviron/water/quality/pdf/iwqmon08.pdf

If you have discharges from your MS4 (regardless of its location) to any of the listed SRPWs or impaired waters (including impaired waters when a TMDL has not been approved), please provide an assessment of the progress towards expanding the MS4 Phase II Stormwater Program to include the discharges to the aforementioned waters and adapting the Six Minimum Control Measures to include the control of stormwater in these areas. Please indicate a rationale for the activities chosen to protect these waters. Please note that all of the measurable goals and BMPs required by the 2003 MS4 General Permit may not be applicable to these discharges.



RHODE ISLAND DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

Office of Water Resources



INSTRUCTIONS FOR THE RI POLLUTANT DISCHARGE ELIMINATION SYSTEM (RIPDES)

SMALL MUNICIPAL SEPARATE STORM SEWER SYSTEMS AND INDUSTRIAL ACTIVITY AT ELIGIBLE FACILITIES OPERATED

BY REGULATED SMALL MS4s

ANNUAL REPORT FORM

WHO MUST SUBMIT AN ANNUAL REPORT:

Owners/Operators of regulated small municipal separate storm sewer systems (MS4s) and industrial activities authorized to discharge stormwater under the Rhode Island Pollutant Discharge Elimination System (RIPDES) Stormwater General Permit for Small Municipal Separate Storm Sewer Systems and Industrial Activity at Eligible Facilities Operated by Regulated Small MS4s (hereafter referred to as "the General Permit"), must submit an Annual Report, outlined in Part IV.G of the permit. The Report must be submitted each year after permit issuance by March 10th to track progress of compliance. If you have questions regarding this Annual Report Form contact Margarita Chatterton of the Rhode Island Department of Environmental Management (RIDEM), Office of Water Resources, Permitting Section at (401) 222-4700 ext. 7605.

The Annual Report must be submitted to:

RIDEM Office of Water Resources RIPDES Program Permitting Section 235 Promenade Street Providence, RI 02908 ATTN: Jennifer Stout

INSTRUCTIONS FOR COMPLETION:

GENERAL INFORMATION PAGE:

"RIPDES Permit #"
Include your permit ID # to ensure proper tracking.

"Operator of MS4"

Give the legal name of the person, firm, public (municipal) organization, or any other entity that is responsible for day-to-day operations of the MS4 described in this application (RIPDES Rules 3 & 12). Enter the complete address and telephone number of the operator. Circle the appropriate choice to indicate the legal status of the operator of the MS4.

"Owner of MS4"

If the owner is the same as the operator do not complete this section. Give the legal name of the person, firm, public (municipal) organization, or any other entity that owns the MS4 described in this application (RIPDES Rules 3 & 12). Do not use a colloquial name. Enter the complete address and telephone number of the owner.

"Certification"

State and federal statutes provide for severe penalties for submitting false information on this application form. State and federal regulations require this application to be signed as follows (RIPDES Rule 12);

For a corporation: by a responsible corporate officer, which means: (i) president, secretary, treasurer, or vice president of the corporation in charge of a principal business function, or any other person who performs similar policy or decision making functions, or (ii) the manager of one or more manufacturing, production, or operating facilities, provided the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long environmental compliance with environmental laws and regulations; the manager can ensure that the necessary systems are established or actions taken to gather complete and accurate information or permit application requirements; and where authority to sign documentation has been assigned or delegated to the manager in accordance with corporate procedures:

For a partnership or sole proprietorship: by a general partner or the proprietor;

For a Municipality, State, Federal or other public site: by either a principal executive officer or ranking elected official.

SECTION I- OVERALL EVALUATION OF BMPS AND MEASURABLE GOALS:

One or more pages, front and back, are provided to report on the status of measurable goals which have been developed to aid in the implementation of strategies, procedures, and programs used to achieve each of the six minimum control measures in Part IV.B of the General Permit. This section provides narrative space for a descriptive explanation and evaluation of the actions taken to satisfy each of the minimum control measures for the 2016 calendar year. Please type or print. If additional space is needed, modify as necessary. Please submit attachments to the appropriate minimum control measure following the format provided.

A Permit ID # has been provided, which refers to the part of the permit where you can find a listing or description of the required measurable goal.

Please provide a general summary of actions taken (implementation of BMPs, development of procedures, events, etc.) to meet the measurable goals of the minimum measure. Be sure to identify parties responsible for achieving each measurable goal and reference any reliance on another entity for achieving any measurable goal. Mark with an asterisk (*) if this person/entity is different from last year.

Describe whether each measurable goal was completed within the time proposed in the General Permit or your Stormwater Management Program Plan (SWMPP). Why or why not? Provide a progress report and discussion of activities that will be carried out during the next reporting cycle to satisfy the requirements of the minimum measures. If applicable, assess the appropriateness of the actions taken to meet the requirements of the minimum measure. In determining appropriateness, you may want to consider at a minimum the local population targeted, pollution sources addressed, receiving water concerns, integration with local management procedures, and available resources and violations or environmental impacts eliminated or minimized.

Also, discuss the effectiveness of the implementation of BMPs to meet the requirements of the minimum measure and the overall effectiveness of the minimum measure. Describe your progress towards achieving the overall goal of reducing the discharge of pollutants. Please include assessment parameters/indicators used to measure the success of the minimum measure. Also include a discussion of any proposed changes to BMPs or measurable goals.

After evaluation, it may be necessary to make changes or modifications to your Implementation Schedule if the time frame, appropriateness or effectiveness cannot be assured. If so, please include descriptions of changes or modifications, and detailed justification in the appropriate sections.

SECTION II- ADDITIONAL ANNUAL REPORT REQUIREMENTS

Section II refers to additional reporting requirements that the General Permit requires to be submitted to the Department as part of the Annual Report. Section II requirements apply to Minimum Control Measures 2 through 6.

Minimum Control Measure #2: Section II:

Specify the date of and how the annual report was public noticed. If a public meeting was needed, provide the date and place. Include a summary of public comments received in the public comment period of the draft annual report and planned responses or changes to the program (new or revised BMP's and measurable goals, partnerships, etc.). Be sure to attach a copy of your public notice (Parts IV.G.2.h and IV.G.2.i) to the Annual Report.

Minimum Control Measure #3: Section II.A:

Provide the number of illicit discharges identified in 2016, number of illicit discharges tracked in 2016, number of illicit discharges eliminated in 2016, complaints received, complaints investigated, violations issued and resolved with a summary of enforcement actions, number of unresolved violations that have been referred to RIDEM, the total number of illicit discharges identified to date, and the total number of illicit discharges remaining unresolved at the end of 2016. Include a short narrative describing the extent to which your system has been mapped (Part IV.G.2.m), and the total number of outfalls identified to date.

Minimum Control Measure #3: Section II.B:

List identified MS4 interconnections, including location, date found, operator of the physically interconnected MS4, and originating source of newly identified physical interconnections with other small MS4s. Also note any planned or coordinated activities with the physically interconnected MS4 (Part IV.G.2.k and IV.G.2.l).

Minimum Control Measures #4 & 5: Section II.A: Identify the number of construction and post-construction plan and SWPPP/SESC Plan reviews completed during Year 13 (2016) and any additional information. This includes, but is not limited to a summary of the reviews, responsible parties, and types of projects reviewed.

Minimum Control Measure #4: Section II.B:

Construction inspection information for erosion and sediment control should be submitted annually as stated in Part IV.G.2.n. Provide a summary of the number of site inspections conducted, inspections that have resulted in enforcement actions, violations that have been resolved and of those unresolved, referred to RIDEM.

Minimum Control Measure #5: Section II.B:

Post-construction inspection information for proper installation of post-construction structural BMPs should be submitted annually as stated in Part IV.G.2.o. This should provide a summary of the number of site inspections conducted, inspections that have resulted in enforcement actions, violations that have been resolved and of those unresolved, referred to RIDEM.

Minimum Control Measure #5: Section II.C:

Inspection information for proper operation and maintenance of post-construction structural BMPs should be submitted annually as stated in Part IV.G.2.p. This should provide a summary of the number of site inspections conducted, inspections that have resulted in

enforcement actions, violations that have been resolved and of those unresolved, referred to RIDEM.

Also include a discussion of any proposed changes to BMPs or measurable goals.

Minimum Control Measure #6: Section II.A:

As prescribed in Part IV.B.6.b.1.i of the General Permit, the MS4 operator must identify and list the specific location and description of all structural BMPs in the SWMPP at the time of application and update the information in the annual report.

Minimum Control Measure #6: Section II.B:

Part IV.B.6.b.1.v of the General Permit states to identify and report annually, as part of the annual report, known discharges causing scouring at outfall pipes or outfalls with excessive sedimentation. Include Outfall ID #, location, description of the problem, any remediation taken, and the ultimate receiving water body.

Minimum Control Measure #6: Section II.C:

As noted in Part IV.G.2.j of the General Permit, specify any planned municipal construction projects or opportunities to include water quality BMPs, low impact development, or seek to promote infiltration and recharge.

Minimum Control Measure #6: Section II.D:

Please include a summary of results of any other information that has been collected and analyzed. This includes any type of data, including, but not limited to, dry weather survey data (Part IV.G.2.e).

TOTAL MAXIMUM DAILY LOAD (TMDL) or other Water Quality Determination REQUIREMENTS

Section I:

Complete this section only if your MS4 is subject to an approved TMDL. TMDL requirements may require the implementation of the six minimum control measures to address the pollutants of concern, and/or additional structural stormwater controls or measures that are necessary to meet the provisions of the approved TMDL. Be sure to identify the approved TMDL and assess the progress towards meeting the requirements for the control of stormwater (Part IV.G.2.d).

Provide a progress report on the present status and discussion of activities that have been accomplished or will be carried out during the next reporting cycle to satisfy the requirements of the TMDL. If applicable, assess the appropriateness of the BMPs selected under each of the six minimum control measures to meet the requirements of the TMDL. In determining appropriateness, you may want to consider violations or environmental impacts eliminated or minimized.

Please include assessment parameters/indicators that will be used to measure the success of the selected BMPs.

SPECIAL RESOURCE PROTECTION WATERS (SRPWs)

Section I:

Complete this section only if your MS4, located outside Urbanized Areas or Densely Populated Areas, discharges to:

a SRPW as listed in Appendix D of the *RIDEM Water* Quality Regulations at this link:

http://www.dem.ri.gov/pubs/regs/regs/water/h20q09a.pdf or

an impaired water body including water bodies with no approved TMDL as listed in Appendix G of the 2008 Integrated Water Quality Monitoring and Assessment Report at this link:

http://www.dem.ri.gov/programs/benviron/water/quality/pdf/iwqmon08.pdf.

In accordance with Rule 31(a)(5)(i)G in the Regulations for the Rhode Island Pollutant Discharge Elimination System (RIPDES Regulations), MS4s were required to incorporate any discharges to these water bodies into their MS4 Program on or after March 10, 2008 unless a waiver has been granted in accordance with Rule 31(g)(5)(iii).

Provide a progress report on the present status and discussion of activities that have been accomplished or will be carried out during the next reporting cycle to incorporate these areas into the MS4's Phase II Stormwater Program.